UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,891,276 B1

Page 1 of 1

DATED

: May 10, 2005

INVENTOR(S) : Cheng-Lien Chiang

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 27,

Line 14, change "TS OP" to -- TSOP --.

Column 30,

Line 38, change "load" to -- lead --.

Column 35,

Line 63, insert -- and -- after "pad,".

Column 36,

Line 63, change "were" to -- wire --.

Signed and Sealed this

Twelfth Day of July, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office